EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	6	("20020145401" "20030062868" "20040036434" "20050174089" "6591925" "6679346").PN.	US-PGPUB; USPAT	OR	OFF	2009/01/06 14:00
L2	5152	(180/170,171,172,197,65.1).CQLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/06 15:34
L3	778	(701/71,74,75).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/06 15:34
L4	3638	(903/942).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/06 15:34
L5	65	(L2 or L3 or L4) and "voltage converter"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/06 15:34
L6	259	L2 and (slip same torque same (module or controller))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/01/06 15:34
L7	11	("2004/0145338").URPN.	USPAT	OR	OFF	2009/01/06 15:36
L8	14	("5159990" "5428539" "5737714" "6182002").PN. OR ("6473683").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/01/06 15:36
L9	14	("5159990" "5428539" "5737714" "6182002").PN. OR ("6473683").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/01/06 15:36
L10	21	("20010032046" "20010054520" "20020084127" "3622973" "3659263" "4335337" "4521856" "4871043" "4989686" "4991679" "5041772" "5103925" "5199325" "5213177" "5318355" "5343970" "5455771" "5476310" "5535124" "5731975" "6473683").PN. OR ("7451847").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2009/01/06 15:36
L11	1	((voltage near2 converter) and motor and "slip detection module" and controller and time and slope).clm.	US-PGPUB	OR	OFF	2009/01/06 15:37
S1	1	"10565851"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/12/03 17:54

S2	34	hommi-akira\$.in.	US-PGPUB;	OR	OFF	2008/12/03
			USPAT; EPO; JPO;			17:55
			DERWENT; IBM_TDB			
S3	5	("20040145338" "5373195" "5492192" "5788005" "6473683").	US-PGPUB; USPAT	OR	OFF	2008/12/07 22:56
		PN.	OOI // I			22.30
S4	5126	(180/170,171,172,197,65.1).CCLS.	US-PGPUB; USPAT; EPO;	OR	OFF	2008/12/07 22:57
			JPO; DERWENT;			
			IBM_TDB			
S5	773	(701/71,74,75).CCLS.	US-PGPUB; USPAT; EPO;	OR	OFF	2008/12/07 22:57
			JPO;			22.37
			DERWENT; IBM_TDB			
S6	3631	(903/942).CCLS.	US-PGPUB;	OR	OFF	2008/12/07 22:57
			USPAT; EPO; JPO;			22.57
			DERWENT; IBM_TDB			
S7	65	(S4 or S5 or S6) and "voltage converter"	US-PGPUB;	OR	OFF	2008/12/07
			USPAT; EPO; JPO;			22:58
			DERWENT; IBM_TDB			
S8	258	S4 and (slip same torque same (module or controller))	US-PGPUB; USPAT; EPO;	OR	OFF	2008/12/07 22:59
		or controllery)	JPO;			22.00
			DERWENT; IBM_TDB			
S9	11	("2004/0145338").URPN.	USPAT	OR	OFF	2008/12/07 23:00
S10	14	: ("5159990" "5428539" "5737714"	US-PGPUB;	OR	OFF	2008/12/07
		"6182002").PN. OR ("6473683").URPN.	USPAT; USOCR			23:01
S11	14	("5159990" "5428539" "5737714" "6182002").PN. OR ("6473683").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/12/07 23:02
S12	21	("20010032046" "20010054520"	US-PGPUB;	OR	OFF	2008/12/07
		"20020084127" "3622973" "3659263" "4335337" "4521856"	USPAT; USOCR			23:03
		"4871043" "4989686" "4991679" "5041772" "5103925" "5199325"				
		"5213177" "5318355" "5343970"				
		"5455771" "5476310" "5535124" "5731975" "6473683").PN. OR				
S13	1	((voltage near2 converter) and motor	US-PGPUB	OR	OFF	2008/12/07
		and "slip detection module" and	00 1 GI 0D		<u></u>	23:13
		controller and time and slope).clm.			1	}

1/6/2009 3:37:24 PM

C:\ Documents and Settings\ jmeyer\ My Documents\ EAST\ Workspaces\ 10565851 vehicle slip control system and method.wsp